

Fig. 5–31. Buick Transmission Gasket.*



Fig. 5–33. Closed-End Wrench. (Draw with type head assigned by instructor.)*



Fig. 5–35. Quadrant for Lathe.*